



30-Jun-2015

Product Retirement Notice – FPS-2-2M & FPS-2-2M/AP Fence-Mounted Intrusion Detection Systems

FPS-2-2M & FPS-2-2M/AP Product Retirement

Senstar herein announces the planned retirement of the FPS-2-2M and FPS-2-2M/AP fence-mounted perimeter intrusion detection systems.

For more than 20 years the FPS-2-2M and FPS-2-2M/AP fence sensors have been providing trusted protection for critical infrastructure facilities around the world. However, given increasing levels of component obsolescence affecting these products and the availability of newer and more advanced Senstar products for fence detection, Senstar is now announcing the following Product Retirement milestones for FPS-2-2M and FPS-2-2M/AP products:

| Date | Milestone |
|--------------|--|
| 30-June-2015 | Product Retirement Notice issued (this document) , affected products are still available for new sales |
| 31-Dec-2016 | Product no longer available for new sales, repair services remain available |
| 31-Dec-2018 | Repair services transition to a Best Effort basis |
| tbd | Complete end of life – all repair services discontinued |

Affected part numbers

The affected part numbers are given in Table 1 below.

Product Migration

For customers wishing to upgrade from the FPS-2-2M and FPS-2-2M/AP fence sensors Senstar recommends either the FlexZone ranging fence intrusion detection system or the FiberPatrol ranging fiber-optic fence detection system.

For further information

Please direct inquiries or requests for quotation to your local Senstar representative – see www.senstar.com for contact information.

Stewart Dewar, Product Manager
Senstar Corporation
119 John Cavanaugh Drive
Ottawa, ON K0A 1L0
T: +1 (613) 839-5572
E: sdewar@senstar.com

Part Numbers Affected by this Product Retirement Notice

| Table 1 – FPS-2-2M and FPS-2-2M/AP Fence Sensor Part Numbers Affected by this Retirement Notice | |
|--|--|
| Part Number | Description |
| | Advanced Processing Multiplex Processor Units |
| 02-130002 | Dual Zone signal processor, multiplex output - FPS-2-2M |
| 02-130003 | Single Zone signal processor, multiplex output, - FPS-2-2MSZ |
| 02-130002-1 | Dual Zone signal processor, multiplex output, EDAPT advanced processing - FPS-2-2M/AP |
| 02-130003-1 | Single Zone signal processor, multiplex output, EDAPT Advanced Processing- FPS-2-2MSZ/AP |
| | Sensor Cable |
| 100MEX | 100 meters (328 Feet)- FPS Sensor cable includes TSK and cable ties |
| 200MEX | 200 meters (656 feet)- FPS Sensor cable includes TSK and cable ties |
| 300MEX | 300 meter (984 feet)- FPS Sensor cable includes TSK and cable ties |
| TSK | Transducer Service Kit - used for cable splicing and/or end-of-line transmission |
| Dow Compound #4 | TSK Sealant - used to seal TSK unit to prevent problems due to moisture - one tube will seal approx. 10 TSK units |
| | Helisensor Cable & Processors |
| 02-130006 | Dual zone signal processor with multiplex output, for Helisensor cable - FPS-2-2MH |
| 02-130007 | Single Zone signal processor with multiplex output, for Helisensor cable - FPS-2-2MSZH |
| 02-130006-1 | Dual zone signal processor with multiplex output, EDAPT processing adapted for helisensor cable - FPS-2-2MH/AP |
| 02-130007-1 | Single Zone signal processor with multiplex output, EDAPT processing adapted for Helisensor cable - FPS-2-2MSZH/AP |
| 100 MHS | 100 meters (328 feet) transducer Sensor cable enclosed in 3/8" flexible conduit. Includes terminator and cable ties. Note: 100 meter sections may be coupled together, with supplied termination/coupling kit, for a maximum of 300 meters (984 ft.) per zone. |
| | FPS Accessories |
| 82-210000 | Telescoping Sensor cable retractor for sliding gates - Telegate - includes Instruction Sheet. |
| 02-180003 | Monitor IV Field test unit (replaces Monitor III). For use with FPS-2-2R, FPS-2-2M, FPS-485, DCU, and SAT. |
| E6FG0300 | NO LONGER AVAILABLE - REPLACED BY 00KT0601 - Uninterruptible Power Supply with Interruption Relay Output Unit for 115VAC input, includes 1 A.hr. gel cell battery, . Output 13.7 VDC @ 1.2 amp. Rated for indoor use only. UPS-PFI |

Part Numbers Affected by this Product Retirement Notice

| Table 1 – FPS-2-2M and FPS-2-2M/AP Fence Sensor Part Numbers Affected by this Retirement Notice | |
|--|---|
| 00KT0601 | Uninterruptible Power Supply with Power Failure Indicator (PFI) and Low Battery Indicator (LBI) relay outputs. For 115VAC input, includes 1 A.hr. gel cell battery. Output 12 VDC (nominal) @ 1.2 amp. Rated for indoor use only. |
| | SPARE PARTS |
| 06-130300-2 | FPS 2-2 Main Board Assembly - Main Board |
| 06-130100 | Zone Processor Board -Zone Processor Board/AP PWA |
| 06-130420 | CEnDe Transponder board for FPS and MPS-4100 |
| G-Condulet Assy | Condulet termination for Helisensor with gland fitting - Condulet-G |
| EOL Condulet | Helisensor Termination / Coupling kit - EOL Condulet |
| E6BA0900 | Replacement circuit board for 00KT0601 UPS |
| GE0393 | Replacement battery for 00KT0601 UPS |
| 6V1AH | Replacement 1 amp-hour battery for UPS-UF1, 00FG0300 and 00FG0400. Two required per system |