

30-Jun-2015

Product Retirement Notice – FPS-2-2M & FPS-2-2M/AP Fence-Mounted Intrusion Detection Systems

04-Mar-2024
Update

FPS-2-2M & FPS-2-2M/AP Product Retirement

Senstar herein announces the complete end-of-life of the FPS-2-2M and FPS-2-2M/AP fence-mounted perimeter intrusion detection systems.

For more than 20 years the FPS-2-2M and FPS-2-2M/AP fence sensors have been providing trusted protection for critical infrastructure facilities around the world. However, given increasing levels of component obsolescence affecting these products and the availability of newer and more advanced Senstar products for fence detection, Senstar is now announcing the following Product Retirement milestones for FPS-2-2M and FPS-2-2M/AP products:

Date	Milestone
30-June-2015	Product Retirement Notice issued (this document) , affected products are still available for new sales
31-Dec-2016	Product no longer available for new sales, repair services remain available
31-Dec-2018	Repair services transition to a Best Effort basis
04-March-2024	Complete end of life – all repair services discontinued

The affected part numbers are given in Table 1 below.

Affected part numbers

For customers wishing to upgrade from the FPS-2-2M and FPS-2-2M/AP fence sensors Senstar recommends either the FlexZone ranging fence intrusion detection system, the FiberPatrol FP1150 ranging fiber-optic fence detection system, FP400 zone-based fiber-optic fence detection system, or the Senstar LM100 combination fence sensor and intelligent lighting system.

Product Migration

For further information

Please direct inquiries or requests for quotation to your local Senstar representative – see www.senstar.com for contact information.

Stewart Dewar, Product Manager
 Senstar Corporation
 119 John Cavanaugh Drive
 Ottawa, ON K0A 1L0
 T: +1 (613) 839-5572, x4344
 E: sdewar@senstar.com



Part Numbers Affected by this Product Retirement Notice

Table 1 – FPS-2-2M and FPS-2-2M/AP Fence Sensor Part Numbers Affected by this Retirement Notice	
Part Number	Description
	Advanced Processing Multiplex Processor Units
02-130002	Dual Zone signal processor, multiplex output - FPS-2-2M
02-130003	Single Zone signal processor, multiplex output, - FPS-2-2MSZ
02-130002-1	Dual Zone signal processor, multiplex output, EDAPT advanced processing - FPS-2-2M/AP
02-130003-1	Single Zone signal processor, multiplex output, EDAPT Advanced Processing- FPS-2-2MSZ/AP
	Sensor Cable
100MEX	100 meters (328 Feet)- FPS Sensor cable includes TSK and cable ties
200MEX	200 meters (656 feet)- FPS Sensor cable includes TSK and cable ties
300MEX	300 meter (984 feet)- FPS Sensor cable includes TSK and cable ties
TSK	Transducer Service Kit - used for cable splicing and/or end-of-line transmission
Dow Compound #4	TSK Sealant - used to seal TSK unit to prevent problems due to moisture - one tube will seal approx. 10 TSK units
	Helisensor Cable & Processors
02-130006	Dual zone signal processor with multiplex output, for Helisensor cable - FPS-2-2MH
02-130007	Single Zone signal processor with multiplex output, for Helisensor cable - FPS-2-2MSZH
02-130006-1	Dual zone signal processor with multiplex output, EDAPT processing adapted for helisensor cable - FPS-2-2MH/AP
02-130007-1	Single Zone signal processor with multiplex output, EDAPT processing adapted for Helisensor cable - FPS-2-2MSZH/AP
100 MHS	100 meters (328 feet) transducer Sensor cable enclosed in 3/8" flexible conduit. Includes terminator and cable ties. Note: 100 meter sections may be coupled together, with supplied termination/coupling kit, for a maximum of 300 meters (984 ft.) per zone.
	FPS Accessories
82-210000	Telescoping Sensor cable retractor for sliding gates - Telegate - includes Instruction Sheet.
02-180003	Monitor IV Field test unit (replaces Monitor III). For use with FPS-2-2R, FPS-2-2M, FPS-485, DCU, and SAT.
E6FG0300	NO LONGER AVAILABLE - REPLACED BY 00KT0601 - Uninterruptible Power Supply with Interruption Relay Output Unit for 115VAC input, includes 1 A.hr. gel cell battery, . Output 13.7 VDC @ 1.2 amp. Rated for indoor use only. UPS-PFI

Part Numbers Affected by this Product Retirement Notice

Table 1 – FPS-2-2M and FPS-2-2M/AP Fence Sensor Part Numbers Affected by this Retirement Notice	
00KT0601	Uninterruptible Power Supply with Power Failure Indicator (PFI) and Low Battery Indicator (LBI) relay outputs. For 115VAC input, includes 1 A.hr. gel cell battery. Output 12 VDC (nominal) @ 1.2 amp. Rated for indoor use only.
	SPARE PARTS
06-130300-2	FPS 2-2 Main Board Assembly - Main Board
06-130100	Zone Processor Board -Zone Processor Board/AP PWA
06-130420	CEnDe Transponder board for FPS and MPS-4100
G-Condulet Assy	Condulet termination for Helisensor with gland fitting - Condulet-G
EOL Condulet	Helisensor Termination / Coupling kit - EOL Condulet
E6BA0900	Replacement circuit board for 00KT0601 UPS
GE0393	Replacement battery for 00KT0601 UPS
6V1AH	Replacement 1 amp-hour battery for UPS-UF1, 00FG0300 and 00FG0400. Two required per system