



30-Jun-2015 FPS-5 Product Retirement

FPS-5 Product Retirement

Senstar herein announces the planned retirement of the FPS-5 fence-mounted perimeter intrusion detection system.

Senstar’s FPS-5 fence sensor has a long history of providing reliable protection to critical infrastructure sites all over the world. However given the availability of newer and better performing alternatives and increasing component obsolescence affecting the FPS-5 product line, Senstar has established the following product retirement timeline for the FPS-5 product line:

Date	Milestone
30-June-2015	Product Retirement Notice issued (this document) , affected products are still available for new sales
31-Dec-2016	Product no longer available for new sales, repair services remain available
31-Dec-2018	Repair services transition to a Best Effort basis
tbd	Complete end of life – all repair services discontinued

Affected part numbers

The affected part numbers are given in Table 1 below.

Product Migration

For customers wishing to upgrade from the FPS-5 fence sensor Senstar recommends either the FlexZone ranging fence intrusion detection system or the FiberPatrol ranging fiber-optic fence detection system.

For further information

Please direct inquiries or requests for quotation to your local Senstar representative – see www.senstar.com for contact information.

Stewart Dewar
Product Manager
Senstar Corporation
T: +1 (613) 839-5572, x4344
E: sdewar@senstar.com

Table 1 – Part Numbers Affected by MX-5000 & MXF-5500 Retirement Notice	
Part Number	Description
	Advanced Processing Multiplex Processor Units
02-130015	Dual Zone Signal Processor with Multiplex Output, EDAPT Advanced Processing, Integrated Fiber Optic Communications, includes manual - FPS-5
02-130018	Single Zone Signal Processor, Multiplex Output EDAPT Advanced Processing, Integrated Fiber Optic Communications, includes manual. - FPS-5/SZ
	Sensor Cable
100MEX	100 meters (328 Feet)- FPS Sensor cable includes TSK and cable ties
200MEX	200 meters (656 feet)- FPS Sensor cable includes TSK and cable ties
300MEX	300 meter (984 feet)- FPS Sensor cable includes TSK and cable ties
TSK	Transducer Service Kit - used for cable splicing and/or end-of-line transmission
Dow Compound #4	TSK Sealant - used to seal TSK unit to prevent problems due to moisture - one tube will seal approx. 10 TSK units
	FPS-5 Helisensor
02-130016	Dual Zone Signal Processor with Multiplex Output, EDAPT Processing Adapted for Helisensor Cable Integrated Fiber Optic Communications, includes manual - FPS-5H
02-130017	Single Zone Signal Processor with Multiplex Output, EDAPT Processing Adapted for Helisensor Cable, includes manual - FPS-5SZH
100 MHS	100 meters (328 feet) transducer Sensor cable enclosed in 3/8" flexible conduit. Includes terminator and cable ties.Note: 100 meter sections may be coupled together, with supplied termination/coupling kit, for a maximum of 300 meters (984 ft.) per zone.
	FPS Accessories
82-210000	Telescoping Sensor cable retractor for sliding gates - Telegate - includes Instruction Sheet.
02-180003-1	Monitor IV Field test unit with Fiber Optic Card. For use with FPS-5, SAFT. - includes carrying case
E6FG0300	NO LONGER AVAILABLE - REPLACED BY 00KT0601 - Uninterruptible Power Supply with Interruption Relay Output Unit for 115VAC input, includes 1 A.hr. gel cell battery, . Output 13.7 VDC @ 1.2 amp. Rated for indoor use only. UPS-PFI

Table 1 – Part Numbers Affected by MX-5000 & MXF-5500 Retirement Notice	
00KT0601	Uninterruptible Power Supply with Power Failure Indicator (PFI) and Low Battery Indicator (LBI) relay outputs. For 115VAC input, includes 1 A.hr. gel cell battery. Output 12 VDC (nominal) @ 1.2 amp. Rated for indoor use only.
02-150400	Uninterruptible Power Supply with Interruption Relay Output - 4 Amp. - UPS-4
	Spare Parts
06-130900	FPS-5 Board Assembly - FPS-5 Main Board
06-130100	Zone Processor Board -Zone Processor Board/AP PWA
06-131400	Spare fiber-optic transponder carrd for FPS-5, SAFT, and SAFT-R
EOL Condulet	Helisensor Termination / Coupling kit - EOL Condulet
G-Condulet Assy	Condulet termination for Helisensor with gland fitting - Condulet-G
E6BA0900	Replacement circuit board for 00KT0601 UPS
GE0393	Replacement battery for 00KT0601 UPS
6V1AH	Replacement 1 amp-hour battery for UPS-UF1, 00FG0300 and 00FG0400. Two required per system