



Product Bulletin No.: 2017PB003A

Open distribution

2-Feb-2017

End of Life Notification – Panther II Buried Cable Intrusion Detection Sensor

Panther II End-of-Life

Senstar herein informs its valued representatives, dealers, and customers of the current status of the Panther II Buried Cable Perimeter Intrusion Detection System.

The Panther II system, first introduced in 2003, has now reached its complete end of life. As of now no further sales, repair services, spare parts, or technical support are available.

Table 1 below lists the part numbers affected by this bulletin.

Product Migration

Senstar's OmniTrax buried cable sensor provides a natural migration path for customers using the Panther II system. OmniTrax is compatible with the same sensor cables as used with Panther II so that when it comes time to upgrade, the high-value buried infrastructure can be preserved.

For further information

Please direct inquiries to your local Senstar representative – see www.senstar.com for contact information.

Stewart Dewar
Product Manager
Senstar Corporation
119 John Cavanaugh Drive
Carp, ON K0A 1L0
T: +1 (613) 839-5572
E: sdewar@senstar.com

Table 1 – Part Numbers Affected by Panther II Retirement Notice

Part Number	Description
A1FG0300	Panther II detection electronics unit
A3KT0200	Pair of mini-load terminators
A3EM0203	Standalone DC power supply, 115/230 VAC, 50/60 Hz input, 12 VDC/100 W output
A3EM0202	High Reliability Standalone DC power supply, 115/230 VAC, 50/60 Hz input, 12 VDC/50 W output